

Copter Service Leipzig



Inspection Report

Asset: Gebäu-
de 1


Reported by:
Nico Günther
n.guenther@copter-leipzig.de

February 24th, 2021 09:24 CET

Contents

Overview	2
Annotations	3

Overview



Gebäude 1

Type: Building


Location: 51.47423000, 12.08439800

Project name: Gebäude

Project date: February 23rd, 2021 17:13 CET

Annotations

Total amount: 9



ID	Annotation type	Severity	Description	Page
11	Uncategorised	4	unbefetigte Fläche	4
10	Uncategorised	1	Befestigte Fläche (Beton Asphalt)	5
8	Uncategorised	3	Abscheider Waschhalle	6
9	Uncategorised	2	Dachfenster elektrisch	7
12	Uncategorised	2	Lagerfläche Schüttgüter/Parkplatz	8
7	Spalling	4	LKW Waage Beton Abplatzungen	9
3	Uncategorised	1	Tor 1 Handbetätigt	9
5	Uncategorised	1	Tor 2 Handbetätigt	10
6	Uncategorised	1	Tor Waschhalle	10



DJI_0267.JPG


Annotations: 1

Camera information

Location: 51.47406,
12.08478

Altitude (AMSL): 155 m

Azimuth: -92.10°



Annotation 11

Annotation type: Uncategorised

Severity level: 4

Description: unbefetigte Fläche



DJI_0268.JPG

Annotations: 1

Camera information

Location: 51.47406,
12.08462

Altitude (AMSL): 155 m

Azimuth: -90.70°



Annotation 10

Annotation type: Uncategorised

Severity level: 1

Description: Befestigte Fläche
(Beton Asphalt)



DJI_0286.JPG

Annotations: 1

Camera information

Location: 51.47438,
12.0848

Altitude (AMSL): 156 m

Azimuth: -90.40°



Annotation 8

Annotation type: Uncategorised

Severity level: 3

Description: Abscheider
Waschhalle

Location: 51.47432, 12.08458

Altitude (AMSL): 104.94 m



DJI_0288.JPG


Annotations: 1

Camera information

Location: 51.47438,
12.08459

Altitude (AMSL): 156 m

Azimuth: -90.40°



Annotation 9

Annotation type: Uncategorised

Severity level: 2

Description: Dachfenster
elektrisch

Location: 51.47419, 12.08443

Altitude (AMSL): 112.01 m



DJI_0292.JPG


Annotations: 1

Camera information

Location: 51.47438,
12.08416

Altitude (AMSL): 156 m

Azimuth: -90.30°



Annotation 12

Annotation type: Uncategorised

Severity level: 2

Description: Lagerfläche
Schüttgüter/Parkplatz



DJI_0371.JPG

Annotations: 4

Camera information

Location: 51.47416,
12.08385

Altitude (AMSL): 154 m

Azimuth: +67.30°



Annotation 7

Annotation type: Spalling

Severity level: 4

Description: LKW Waage Beton
Abplatzungen

Location: 51.47431, 12.08404

Altitude (AMSL): 104.9 m



Annotation 3


Annotation type: Uncategorised

Severity level: 1

Description: Tor 1 Handbetätigt

Location: 51.47426, 12.08418

Altitude (AMSL): 108.69 m



Annotation 5

Annotation type: Uncategorised

Severity level: 1

Description: Tor 2 Handbetätigt

Location: 51.4742, 12.08426

Altitude (AMSL): 107.05 m



Annotation 6

Annotation type: Uncategorised

Severity level: 1

Description: Tor Waschhalle

Location: 51.47416, 12.08431

Altitude (AMSL): 108.11 m